

Fig. 1

'No Pass' Scenario




Fig. 2

<u>Time/Date</u>	<u>Supported Tests</u>	<u>Status</u>
3/17/01 21:23	Misfire Monitoring	complete
	Fuel System Monitoring	complete
	Component Monitoring	complete
	Catalytic Monitoring	complete
	Evaporative System Monitoring	complete
	Oxygen Sensor Monitoring	complete
	Oxygen Sensor Heater Monitoring	complete
	EGRA System Monitoring	complete
3/18/01 12:25		

2




Fig. 4

'Pass' Scenarios




Fig. 5




Fig. 6

<u>Time/Date</u>	<u>Supported Tests</u>	<u>Status</u>	<u>Odo. (miles)</u>	<u>State</u>	<u>Time/Date</u>	<u>Supported Tests</u>	<u>Status</u>	<u>Odo. (miles)</u>	<u>State</u>
3/17/01 21:23	Misfire Monitoring Fuel Systems Monitoring Comprehensive Component Monitoring Catalyst Monitoring Evaporative System Monitoring Oxygen Sensor Monitoring Oxygen Sensor Heater Monitoring EGR System Monitoring	complete complete complete complete complete complete complete	0	A	3/18/01 13:28	Misfire Monitoring Fuel Systems Monitoring Comprehensive Component Monitoring Catalyst Monitoring Evaporative System Monitoring Oxygen Sensor Monitoring Oxygen Sensor Heater Monitoring EGR System Monitoring	complete complete complete complete complete complete complete	65	D
3/18/01 12:25	Misfire Monitoring Fuel Systems Monitoring Comprehensive Component Monitoring Catalyst Monitoring Evaporative System Monitoring Oxygen Sensor Monitoring Oxygen Sensor Heater Monitoring EGR System Monitoring	incomplete incomplete incomplete incomplete incomplete incomplete incomplete	1	B	3/19/01 19:55	Misfire Monitoring Fuel Systems Monitoring Comprehensive Component Monitoring Catalyst Monitoring Evaporative System Monitoring Oxygen Sensor Monitoring Oxygen Sensor Heater Monitoring EGR System Monitoring	complete complete complete incomplete complete complete complete	231	D
3/18/01 12:47	Misfire Monitoring Fuel Systems Monitoring Comprehensive Component Monitoring Catalyst Monitoring Evaporative System Monitoring Oxygen Sensor Monitoring Oxygen Sensor Heater Monitoring EGR System Monitoring	complete complete complete incomplete complete complete complete	22	C	3/20/01 6:23	Misfire Monitoring Fuel Systems Monitoring Comprehensive Component Monitoring Catalyst Monitoring Evaporative System Monitoring Oxygen Sensor Monitoring Oxygen Sensor Heater Monitoring EGR System Monitoring	complete complete complete complete complete complete complete	244	A
3/18/01 13:17	Misfire Monitoring Fuel Systems Monitoring Comprehensive Component Monitoring Catalyst Monitoring Evaporative System Monitoring Oxygen Sensor Monitoring Oxygen Sensor Heater Monitoring EGR System Monitoring	complete complete complete incomplete complete complete complete	54	D					

Fig. 7

KNOW WHAT YOUR CAR IS THINKING.™

1998 TOYOTA CAMRY

Jane Doe

2001 TOYOTA COROLLA

VIN: WFOCA2983XS651063

Back to Vehicle Check

239

Last CARReader Update: Jan 26 08:35:35 PST

Vehicle Mileage: 13096 miles

Vehicle-Related Information

Inspection / Maintenance

Found 7 entries with information on your vehicle's performance.

230

220

222

224

226

220	205	206	208	210	212	214	216	218
222	205	206	208	210	212	214	216	218
224	205	206	208	210	212	214	216	218
226	205	206	208	210	212	214	216	218

Fig. 8